

Inspection Report **Minerals Regulatory Program**

Report Date
August 2, 2010

Supervisor ATJ

Mine Name: Crescent Creek/May Day Mill
Operator Name: Martinique Mining

Permit number: S/017/043
Inspection Date: July 27, 2010
Time: 10:45 -11:50 AM

Inspector(s): Wayne Western

Other Participants: Buzz Rakow -BLM, Kathy Anders - BLM, Sakkie Eichorn - Permittee, Shane Scott - Permittee

Mine Status: Active

Weather: Mostly clear, 80's

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

1. Permits, Revisions, Transfer, Bonds

The Division reviewed the bond amount and determine that it needs to be escalated to 2013 or 2015 dollars.

2. Public Safety (shafts, adits, trash, signs, highwalls)


The site contains some processing equipment. The site had been cleanup compared to the last inspection. The Division's camera was not working.

Conclusions and Recommendations:

The Division should follow up on the bond and continue to monitor the site.

Inspection Date: July 27, 2010
Page 2 of 2
S/017/043

Inspector's Signature



Date: August 2, 2010

PBB:whw:pb

cc: Permittee

Buzz Rakow, Hanksville BLM

O:\M017-Garfield\S0170043-CrescentCreek\inspections\Ins-S0170043-07272010.doc